


Width measurement bar

Replacing the IR sensors






1 Remove covers



2 Remove Teflon rollers




P/N 111812 - \$270.95  
Part consists of IR sensor and circuit board




Plastic sleeves!

Install new sensor and board

LED! Orientation



5 Adjust gap!



Middle position

LED green: stand by

LED yellow: status

6 Re-install teflon rollers and covers